

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2552	(motor and winding and stator and rotor and (speed or run\$4) and test\$4 and voltage)	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:28
L2	33	1 AND RUNOUT	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 16:52
L3	2	(motor and winding and stator and rotor and (speed or run\$4) and test\$4 and voltage).ab.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 16:36
L4	13	(motor and winding and stator and rotor and (speed or run\$4) and test\$4 and voltage).clm.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 16:36
L5	0	2 AND 3	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 16:36
L6	1	2 AND 4	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 16:36
L7	27	1 AND RUNOUT AND energiz\$4	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:02
L8	3	1 AND RUNOUT AND (NON ADJ energiz\$4)	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 16:52
L9	20	1 AND RUNOUT AND energiz\$4 AND FREE\$2	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:09
L10	2	1 AND RUNOUT AND energiz\$4 AND (ROTOR NEAR2 FREE\$2)	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:04
L11	22	1 AND RUNOUT AND energiz\$4 AND INDUC\$4	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:08
L12	19	1 AND RUNOUT AND energiz\$4 AND FREE\$2 AND INDUC\$4	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:25
L13	16	1 AND RUNOUT AND energiz\$4 AND FREE\$2 AND INDUC\$4 AND (spindle NEAR2 motor)	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:26
L14	1	13 AND 4	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:26
L15	44	1 AND STATOR ADJ SIDE	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:29

EAST Search History

L16	1	13 AND 15	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:29
L17	35	15 AND INDUC\$4	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:29
L18	1	15 AND (VOLTAGE WITH ROTOR WITH FREE\$2).CLM.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:30
L19	50	(VOLTAGE WITH ROTOR WITH FREE\$2).CLM.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:30
L20	3	(VOLTAGE WITH ROTOR WITH (RUN\$4 ADJ FREE\$2)).CLM.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:35
L21	0	(VOLTAGE WITH ROTOR WITH (RUN\$4 ADJ FREE\$2)).AB.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:35
L22	0	(VOLTAGE WITH ROTOR WITH (RUN\$4 ADJ FREE\$2)).TI.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:38
L23	8	(RUNOUT WITH (ROTOR OR MOTOR)).TI.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 18:17
L24	10	("3488581" "3889504" "4183060" " 4300226" "4527263" "4527263" "53 65458" "5761821" "6683744" "6895 656").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 17:48
L25	10	("3604248" "4495448" "5171984" " 5262717" "5864238" "6035263" "60 46602" "6452416" "6563281" "6642 739").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 18:18
L26	68	((SPIN OR SPINDLE) ADJ MOTOR) NEAR2 TEST\$4	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 18:37
L27	68	(((SPIN OR SPINDLE) ADJ MOTOR) NEAR2 TEST\$4)	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 18:37
L28	2	(((SPIN OR SPINDLE) ADJ MOTOR) NEAR2 TEST\$4) AND (MOTOR ADJ MOUNT)	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 18:38
L29	0	((rotational with position with rotor) and runout).clm.	USPAT	OR	OFF	2006/10/28 19:42
L30	12	(rotational with position with runout).clm.	USPAT	OR	OFF	2006/10/28 19:43
L31	0	(rotational with position with runout).ti.	USPAT	OR	OFF	2006/10/28 19:43

EAST Search History

L32	4	(rotational with position with runout).ab.	USPAT	OR	OFF	2006/10/28 19:45
L33	2	30 and 32	USPAT	OR	OFF	2006/10/28 19:45
S1	13	(motor and winding and stator and rotor and (speed or run\$4) and test\$4 and voltage).clm.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 16:36
S2	2	(motor and winding and stator and rotor and (speed or run\$4) and test\$4 and voltage).ab.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/28 16:36
S3	1	"20040212392"	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/27 13:21